Rosemary Inn, Dresmerie Cabin (Bldg. No. 374) Olympic National Park Barnes Point, Lake Crescent Port Angeles Vicinity Clallam County Washington HABS No. WA-185-C

HABS WASH 5-POANN, SY-

THOTOXIRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA


Historic American Building Survey National Park Service Western Region Department of the Interior San Francisco, California 94107

NATIONAL PARK SERVICE Department of the Interior

HISTORIC AMERICAN BUILOING SURVEY ARCHITECTURAL DATA FORM

STATE	COUNTY	TOWN OR VIC	INITY
SIAIL	Approximately 20 miles southwest of		
WASHINGTON	CLALLAM	Port Ang	النظال الخارات في الخراج و الخراج و المراج و
HISTORIC NAME OF STRUCTURE (in		name)	HABS NO.
Rosemary Inn, "Dreamerie" Cabin WA-185-C			
SECONDARY OR COMMON NAMES OF STRUCTURE			
Bldg. No. 374			
COMPLETE ADDRESS (for rural sites describe location) Barnes Point, south shore of Lake Crescent, north side of Hwy 101, approximately 20 miles from Port Angeles, in Olympic National Park.			
DATE OF CONSTRUCTION (include source) ARCHITECT(S) (include source)			
		Builder and Craftsman:	
Late 1920s (Historic Structure Report) John Dann (HRS, 1983) SIGNIFICANCE (architectural and historical, include original use of structure)			
This cabin was constructed as an integral part of the Rosemary Inn Complex. It			
contributes to the overall character of the rustic, picturesque resort ensemble and			
possesses integrity of design, materials, workmanship, location, setting, feeling and			
association.			
STYLE (if appropriate)			
Craftsman-style cottage			
MATERIAL OF CONSTRUCTION (include structural systems)			
Wood-frame construction set on 6 x 6 wood posts on concrete blocks and piers.			
SHAPE AND DIMENSIONS OF STRUCTURE (sketched floor plans on separate sheet acceptable)			
Square: 19' x 19'			
EXTERIOR FEATURES OF NOTE 1-story; wood-shingled jerkin-head roof with slightly extended eaves supported by Knee			
braces; exposed rafter ends; wood shingle siding with sawtooth cut wood boards above on			
gable ends; gable-roofed entry overhang on north supported by knee braces; recessed entry on north; shed-roof porch on south facade with log supports; 3-over-1 casement sash;			
llattice skirting.			
INTERIOR FEATURES OF NOTE (describe floor plans if not sketched)			
Bathroom construction original; painted floor boards; 2 sleeping rooms divided by			
partition; vertical wood board wainscotting with 3 1/4" bevelled siding above (painted).			
MAJOR ALTERATIONS AND ADDITIONS, WITH DATES			
Complete rehabilitation of cabin, 1987			
PRESENT CONDITION AND USE			
Excellent; seasonal housing			
OTHER INFORMATION AS APPROPRIATE			
SOURCES OF INFORMATION (include listing on National Register, State Registers, etc.)			
Historic Structure Report 1986 - Matigual Register Listing, 1979 Historic Resource Study 1983			
Historic Building Inventory 1983			
COMPILER, AFFILIATION	Davide Correspon		DATE July, 1988
Gretchen A. Luxenberg, National	rark Service	1	oury, 1200

ROSEMARY INN, DREAMERIE CABIN (Bldg. No. 374) HABS No. WA-185-C (page 2)





Dreamerie Building #374